



TRUpour Limited,
Templemichael Business Park,
Longford, Ireland
[t] +353 43 42005 [f] +353 43 42006
www.TRUpour.com

FOB Operating Instructions

When keg empties FOB shuts off keeping beer line full to faucet at bar!

Changing the Keg



Step 1 Disconnect empty keg and tap new keg

Step 2 Push vent until chamber is full of clear beer
[Hold vent as shown for 10 seconds]



Step 3 Turn lever to up position to lift float



Step 4 Turn lever to down position for normal operation
[If frothy beer appears repeat Step 2]

Cleaning the Beer Line



Step 1 Turn lever to up position whilst cleaning
[Clean the beer line]
[Bypass FOB when using sponge pellets]



Step 2 Turn lever to down position for normal operation